



Everwin Pneumatic Corporation

No.7 Wugong 7th Rd. Taichung 41353 Taiwan
T: +886-4-2333 2999; F: +886-4-2333 0555



SAFETY BULLETIN – SCN65

Issue Description

We have discovered a potential premature failure with the top section of the CAP unit (see Figure A). When used beyond the recommended operating pressure and beyond the intended use of the tool, there is a possibility that the top section of the cap can crack at the exhaust port section and that it can eventually separate from the main body of the cap unit.

Fix

Users who have exposed their tool to these conditions should stop using the SCN65 and contact your nearest Bissett Fasteners location for a free cap replacement. While there have been no safety incidents reported since the launch of the tool in 2016, Everwin believes that as a preventative measure, the cap should be replaced. We anticipate the new caps to be available in the first quarter of 2020. We understand and recognize the inconvenience this product nonconformance has caused you and asks for your cooperation in completing the necessary precautionary fix.

	
SCN65 - Siding Coil Nailer - 2-1/2" (65mm)	Figure A - CAP Unit

Manufacturer:	Everwin Pneumatic Corporation
Model:	SCN65 - Siding Coil Nailer - 2-1/2" (65mm)
Manufactured in:	Taiwan

CANADIAN DISTRIBUTOR

To locate your nearest Bissett location please refer to the contact information below

Bissett Fasteners Limited
Website:
Phone:

Exclusive distributor of Everwin products in Canada
www.bissettfasteners.ca
604-540-0200